



We've got the builders in...

Bulletin 3 - February 2018

Work has been progressing deep inside the Museum over the past weeks:

- * the new raised floor and ramp down through the Magazine into the main exhibition area has been completed and finished with non-slip vinyl covering, together with a stainless steel balustrade;
- * new steel fire-doors have been fitted to allow step-free access out of the Museum into the Moat;
- * Museum Volunteers have moved the heavy exhibits out of temporary storage back into the Museum and the work cleaning and re-setting the exhibits has started;
- * Volunteers are fitting corrugated ceiling panels to help reduce damage to exhibits caused by rain seeping through the promenade decking and the Tower Walls.

The next stages include:

- * the installation of the lift; the ramped footbridge across the moat, and the new entrance gates.

We apologise that the work has taken longer than we had hoped, but it shouldn't be too long now!